Ref: DGCAR/3/3/4/37/2025 Date: 10th June 2025



To: Capt. Tariq Al Harthy Director of Training Salam Air P.O. Box 3802, P.C. 111 Sultanate of Oman

After Compliments,

Subject: SEP Drills Recurrent - Request for Extension

With reference to your letter OV-CAA-OPS-1715 dated 16th June 2025, on the above request, due to the current challenges around the country and the training facility slots unavailability.

The supporting documents (Recovery Plan) were reviewed that was affecting the practical Emergency Evacuation training scenarios, covering failure of power assist systems where fitted, and including the action and forces required to operate and deploy evacuation slides (Appendix 1 to CAR OPS-1.1015 Recurrent training (c) (2)/ Fire Fighting and Swimming.

Given the importance of maintaining proficiency in Safety Emergency Practical Drills, the extension period will be granted until 31" December 2025, to enable Salam Air to facilitate adequate preparation and participation of all 134 Flight and Cabin Crew members that was in the name list as per your request.

Monitoring and Evaluation in Accordance with the Training Recovery Plan

As per the Training Recovery Plan for SEP Drills for 36 months and the Refresher training. The Flight and Cabin crew will be monitored and evaluated during the ground training and on-board the Aeroplane to ensure they are up to competent level.

- To ensure compliance with these regulations, the (CAA) inspectors will conduct thorough monitoring and evaluation of SEP training programs. As part of this oversight, the CAA inspectors observe and assess the SEP ground training to verify that a required procedure are adequately covered and the training standards are met.
- Additionally, CAA inspectors perform on-board evaluations during actual flight operations. These evaluations
 involve monitoring cabin crew performance on-board to ensure that they can effectively execute and maintain
 safety standards during flight. This dual approach combining ground training assessments with in-flight
 evaluations ensure that the flight and cabin crew members are fully prepared to handle emergency situations.
- This extension is valid for the attached crew list.

Yours sincerely,

Rawya Nasser Hamed Al-Ada Act. Director General of Civil Aviation Regulations ALDII ODIO

H.E CAA President Office

P.O. Box: 1, P.C.: 111, Muscat – Sultanate of Oman

صندوق البريد: 1 ، الرمز البريدي: 111 مسقط - سلطنة عُمان

UND/

+968 24354441/2 - Fax: +968 24354544 - www.caa.gov.om



Part A1 – Application for Exemption

Details of Applicant				
Applicant's Name	SalamAir SAOC			
Applicant's Address	Muscat Hills Building, Head office 3802			
Certificate/Approval/License Number	AOC No.: OMS 005			
Certificate/Approval/License Expiry Date	Valid until suspended or revoked			

efere	ences to	the sp	Particulars of Requested Ex ecified requirements in the applicable reg		ules, implementing standards	
		133	directive from which exemption	n are sough	t de la constant de la constant	
CAR etc.) Details of Regulatory Requirement						
Apper	ndix 1 to 1.965, 3	CAR	As per Appendix 1 to CAR-OPS 1.1015 (c), 1.955 (iii), the following SEP Drills need to be conducted for crew every 3 years. crew required to practice the SEP practical Drills 1- Operation and Opening of all Passenger Evacuation Exits (OM D Section 2.2 Ch 6.3.1.1) 2- Normal Door Operation Performance 3- Emergency Door Operation Performance 4- Hatch Exit Performance 5- Fire and Smoke (OM D Section 2.2 Ch 6.3.1.2) 6- Slide Raft Training (OM D Section 2.2 Ch 6.3.1.3) 7- Life Jacket and Diching Drills 8- Evacuation Slide Training (OM D Section 2.2 Ch 6.3.1.4)			
Deta			on, aircraft or aeronautical product, or typ nd of material, or service or kind of service	The second se	the second se	
•		interest		Denk	OED Daill Evaluated	
Sr.	ID		CABIN CREW NAMES	Rank	SEP Drill Expiry date	
1.	392		A ALI KHALFAN AL NADABI	CA	30/06/2025	
1. 2.	The state of the			COC DAY LANAS		
1. 2. 3.	392	AHL	A ALI KHALFAN AL NADABI	CA	30/06/2025	
1. 2. 3. 4.	392 834	AHL	A ALI KHALFAN AL NADABI EM SOUISSI	CA CS	30/06/2025 30/06/2025	
1. 2. 3.	392 834 844	AHLI WAC MOH	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI	CA CS CA	30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5.	392 834 844 843	AHLI WAC MOH	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI	CA CS CA CA CA	30/06/2025 30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5.	392 834 844 843 842	AHLI WAC MOH QUS JULA	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI AI AL KHANJARI	CA CS CA CA CA CA	30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5. 6.	392 834 844 843 843 842 98	AHLI WAC MOH QUS JULA JOSI	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI AI AL KHANJARI AND JAN MOHAMED AL BALUSHI	CA CS CA CA CA CA CA CS	30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5. 6. 7.	392 834 844 843 842 98 70	AHLI WAC MOH QUS JULA JOSI SAID	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI AI AL KHANJARI AND JAN MOHAMED AL BALUSHI EPHINE DEL SOCORRO PESIGAN	CA CS CA CA CA CA CA CS CS	30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5. 6. 7. 8.	392 834 844 843 842 98 70 527	AHLI WAC MOH QUS JULA JOSI SAID TARI	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI AI AL KHANJARI AND JAN MOHAMED AL BALUSHI EPHINE DEL SOCORRO PESIGAN D KHALIFA AL ADAWI	CA CS CA CA CA CA CS CS CS CA	30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025	
1. 2. 3. 4. 5. 6. 7. 8. 9.	392 834 844 843 842 98 70 527 536	AHLI WAC MOH QUS JULA JOSI SAID TARI ESR	A ALI KHALFAN AL NADABI EM SOUISSI DAS AL BALUSHI IAMMED AL HARTHI AI AL KHANJARI AND JAN MOHAMED AL BALUSHI EPHINE DEL SOCORRO PESIGAN D KHALIFA AL ADAWI IQ AHMED AL ZADJALI	CA CS CA CA CA CA CS CS CS CS CS	30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025 30/06/2025	

23 Sep 2020



13.	865	DUANGHATAI DENDUANGJAI	CA	30/06/2025
14.	913	AFFAN ALBALUSHI	CA	30/06/2025
15.	914	ALLAA AL KHALASI	CA	30/06/2025
16.	915	MARWA ALHARTHY	CA	30/06/2025
17.	917	JANI NIXON PULIKKOTTIL	CA	30/06/2025
18.	920	FATEMEH SADEGHI	CA	30/06/2025
19.	919	MAHMOOD ALHOOTI	CA	30/06/2025
20.	918	LUBEYNA HILAL	CA	30/06/2025
21.	916	JUAIRIN S. UBAY	CA	30/06/2025
22.	292	GHADA BAKHIT AL MUKHAINI	CA	30/06/2025
23.	293	MAATHER OMAR AL BALUSHI	CS	30/06/2025
24.	367	TIANY KAY TADINA	CS	30/06/2025
25.	366	MARIANNE GERONGCA HULAR	CA	30/06/2025
26.	365	SARAH ABDULHALEEM AL KHATIB	CS	30/06/2025
27.	470	ZAINAB ABDULLAH ALTAMTAMI	CS	30/06/2025
8.	473	AHMED AMAR ALHARTHY	CA	30/06/2025
9.	64	ZAYID OBAID AL BULUSHI	CS	31/07/2025
0.	899	AMMAR NASSER AL SIYABI	CA	31/07/2025
1.	896	RAZIA ARIF	CA	31/07/2025
2.	878	SREELAKSHMI KADAMPATTU	CA	31/07/2025
3.	871	PIMONNAT CHIANGFAI	CA	31/07/2025
4.	864	SUPITCHAYA KHAMSUWAN	CA	31/07/2025
5.	862	SIRIPHATSORN DACH-IN	CA	31/07/2025
6.	861	CHAIYA-AMORN KRISANAPRON	CA	31/07/2025
7.	857	NIRACHA PONGPAKDEE	CA	31/07/2025 AUTO
8.	856	SHREE SRIDHARAN	CA	31/07/2025
9.	855	SATARUPA PAUL	CA	31/07/2025
0.	467	MASHAIL ILIAS ALBALUSHI	CA	31/08/2025
1.	38	WESSAM SALAHEDIN ABDEGELIL	CS	31/08/2025
2.	66	OMRAN MOHAMED	CS	31/08/2025
3.	46	BIANCA JOY REGULACIO	CS	31/08/2025
ion p 20		DGCAR Application for	Exemption	



44. 40		ISLAM MAMLOUK RASHED	CS	31/08/2025
45.	594	NAFISEH KARAMALI	CS	30/09/2025
46.	570	ABDULAZIZ ALMAWALI	CS	30/09/2025
47.	541	MIRAJ AL ZADJALI	CA	30/09/2025
48.	537	ZAKARIYA ABDULMONEM AL ABRI	CS	30/09/2025
49.	535	AWATIF AHMED AL SHEHHI	CA	30/09/2025
50.	531	MAHMOOD AL HARBI	CS	30/09/2025
51.	530	SALMAN AL BALUSHI	CS	30/09/2025
52.	528	MOHAMED AL QASMI	CA	30/09/2025
53.	934	NAPHATHON WATCHARATHIRACHINDA	CA	30/09/2025
54.	932	MUSAAB AMUR MASOUD ALSHARJI	CA	30/09/2025
55.	931	ALI YOUSUF AL BALUSHI	CA	30/09/2025
56.	930	MUSTAFA NABI GULMOHAMMED	CA	30/09/2025
57.	928	ADIL FOAD MOTTAHED	CA	30/09/2025
58.	927	NIYLA HAMOOD ALSIYABI	CA	30/09/2025
59.	926	RABIA AFSHEEN MUHAMMAD	CA	30/09/2025
60.	925	ATEFE ABDULREZA HAFTLANG	CA	30/09/2025
61.	1203	AMJAD ALI ALKHAYARI	CA	30/09/2025
62.	599	MIRHOSSEINY, SEYEDE FATEMEH	CS	30/09/2025
63.	586	HANNAT AL ABDUL SALAM	CA	30/09/2025
64.	568	OMAR AL QASMI	CS	30/09/2025
65.	324	SOAR ABBAS	CS	30/09/2025
66.	323	MARYAM CHANDIO	CS	30/09/2025
67.	71	JURAIRAT SUKPIA	CS	30/09/2025
68.	42	MEDILIN VOLUNTAD ALCANTARA	CS	30/09/2025 AUTO
69.	103	NEHAD ABDELMAGEED DAPOH	CS	30/09/2025
70.	62	JIHAD AHMED AL ZADJALI	CS	30 09 2025
71.	405	FAWAZ IBRAHIM AL SHIBLI	CA	30/09/2025
72.	39	NAZEEH HUSSIEN HASSAN	CS	30/09/2025 10012
73.	469	MARYAM HILAL ALMAMARI	CA	30/09/2025

Revision 02 23 Sep 2020



	846	SALAH EL MAHJOUB	CP	30/06/2025
Sr.	ID	FLIGHT CREW NAMES	Rank	SEP Drill Expiry date
	719	NOOH AL BULUSHI	CA	31/10/2025
101.	718	HISHAM FARAH BAIT JABAL	CA	31/10/2025 ET DEPA
100.	720	MARYAM AL HAJRI	CA	31/10/2025 2
90. 99.	721	MARYAM AL HINAI	CA	31/10/2025
97. 98.	723	WAHEEDA AL AGHALANY	CA	31/10/2025= 4401
96. 97.	725	SARA SALIM AL HASANI	CA	31/10/2025 Junio
95.	726	AHMED SAID AL GHEFEILI	CA	31/10/2025
94.	598	SHAMIM REZANIA	CA	31/10/2025
93.	602	MARYAM GHODS	CA	31/10/2025
92.	76	AYOUB DAWOUD AL MUHARRAMI	CS	31/10/2025
91.	937	SIRINE DHOUIB	CA	31/10/2025
90.	939	KHOULOUD HAJ FRAJ	CA	31/10/2025
89.	941	RANIA JAWHER	CA	31/10/2025
88.	943	OUMEIMA HIDOURI	CA	31/10/2025
87.	944	SOUAD ALABCHAR	CA	31/10/2025
86.	945	ASYANUR KURTOGLU	CA	31/10/2025
85.	947	ROSALIE DENA	CA	31/10/2025
84.	948	FATEMEH REZANIA	CA	31/10/2025
83.	949	JENNY SENA QUAYZON	CA	31/10/2025
82.	952	BALQEES AHMED AL HABSI	CA	31/10/2025
81.	566	JAWAHER AL HARTHY	CA	30/09/2025
80.	587	HANIEH NAJAFZADEH HANIEH	CS	30/09/2025
79.	386	AHMED AL KITANI	CS	30/09/2025
78.	538	MOHSEN MABROOK AL GHAWI	CA	30/09/2025
77.	544	MAJID AL ZADJALI	CS	30/09/2025
76.	574	MARWAN AL GHAFRI	CA	30/09/2025
	557	MANSA ESPANANI	CS	30/09/2025
75.	600 597	NASTARAN MIRZAEI MAHSA ESFAHANI	CS	30/09/2025



_				
2.	845	ARUN DAVID REGO	CP	30/06/2025
3.	494	4 KESKES, BACEM CP 30/		30/06/2025
4.	716	ASIF, MUHAMMAD	CP	31/07/2025
5.	508	08 LAABIDI, FAYCAL CP 31/07		31/07/2025
6.	1040	KHATEREH GHODRAT	FO	31/07/2025
7.	1039	HASSAN EL SHEIKH	FO	31/07/2025
8.	888	AMIR FRIKHA	CP	31/07/2025
9.	884	MOHAMED MECHMECHE	CP	31/07/2025
10.	883	PRITISH MISHRA	CP	31/07/2025
11.	882	RAJBIR SINGH	CP	31/07/2025
12.	880	HANANTAJI TAMA	CP	31/07/2025
13.	715	ABDULSAMAD, MOHAMED	CP	31/08/2025
14.	713	KUMAR, BHUPENDERA	CP	31/08/2025
15.	709	AL RIYAMI, RASHID	CP	31/08/2025
16.	333	AL HINAI, HAMID	CP	30/09/2025
17.	332	AL TOKY, SOUD	CP	30/09/2025
18.	330	AL HARTHY, TARIQ	CP	30/09/2025
19.	965	MOHAMED OSMAN SAYED	CP	31/10/2025
20.	964	ZIED ZEDDINI	CP	31/10/2025
21.	962	MOHAMED DEROUICHE	CP	31/10/2025
22.	957	JAMIL HAMDAN	FO	31/10/2025
23.	956	HAITHAM AMMAR	CP	31/10/2025
24.	630	VUUREN, FRANCOIS	CP	30/11/2025
25.	729	BEN IBRAHIM, YOUSEF	FO	30/11/2025
26.	639	RIZVI, IRFAN	CP	30/11/2025
27.	636	BOUGAMRA, MAHER	СР	30/11/2025. AUT
28.	635	BOUKADIDA, SEIFEDDINE	CP	30/11/2025
29.	634	AL HARTHY, FAHAD	CP	30/ 1/2025
30.	816	AL SHANFARI, SAID	FO	31/12/2026
31.	760	AL AISRI, SULAIMAN	FO	31/12/2025
32.	1242	MAHER NASSER AL WAHAIBI	FO	31/12/2025

Revision 02 23 Sep 2020 DGCAR Application for Exemption

5



of flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unable schedule the above crew for SEP Drills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & Ctool and the operation of the functions of the functions 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and add:Hortar attendant panel).	33.	1240 THAMIR MA	ASOUD AL MUSALAMI	FO	31/12/2025	
The SEP drills Recurrent of the crew (list attached in the letter) will be expire from June 2025 to December 2025 Due to Current situation around the country situation, and travel restrictions and the training slots availability, resump of flights on a limited scale form June and also due to the limited number of frequencies of the flights. we are unab schedule the above crew for SEP Drills Recurrent. Proposal Will crew mentioned in the attached letter are current on type. As all our crew have done SEP Initial in an approved raining facilities by CAA, we kindly request you to extend the validity of their SEP Drills. Risk Mitigating Factors Based on training facility current availability: 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARNING, DPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. Perform Pilots Incapacitation 5. open and close sliding window. 6. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Nee to Current situation around the country situation, and travel restrictions and the training slots availability, resump flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unab chedule the above crew for SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted . Septiment's pre-flight check by removing the safety equipment's . Trainees will practice normal door operation . Septiment's pre-flight check by removing the safety equipment's . Trainees will preserve on the functions . Septiment's pre-flight check by removing the safety equipment's . Statey equipment's fre-flight check b		If the exemption w	ill affect a particular kind of ope	eration, details	of such operation.	1.2.2
Due to Current situation around the country situation, and travel restrictions and the training slots availability, resumpt of flights on a limited scale from June and also due to the limited number of frequencies of the flights. we are unab schedule the above crew for SEP Drills Recurrent. Proposal Based on training facilities by CAA, we kindly request you to extend the validity of their SEP Drills: Risk Mitigating Factors Based on training facility current availability: 1. SEP instructor will conduct a theory training and take the trainces for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Phots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resumpt flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unable chedule the above crew for SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat 1 accodance with the exemption is raicraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING, OPENING 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Phots Incapacitation 5. Defamiliar of Cockpit door and the functions 5. Aistery equipments pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aitcraft communi	Backgr	ound				
of flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unab schedule the above crew for SEP Dnils Recurrent. Proposal All crew mentioned in the attached letter are current on type. As all our crew have done SEP Initial in an approved raining facilities by CAA, we kindly request you to extend the validity of their SEP Dnils: Risk Mitigating Factors Based on training facility current availability: 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Traines will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Priots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resump flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unable chedule the above crew for SEP Dnils Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operation 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit: 2. Trainees will practice normal door operation consisting (ARNING, DISARMING, OPENING, OPENING, OPENING, OPENING 4. SEP instructor will conduct a theory training and take the trainees for aircraft visit: 2. Trainees will practice normal door operation consisting (ARNING, DISARMING, OPENING, OPENING, OPENING, OPENING, OPENING, OPENING 5. operand close stid	The SE	P drills Recurrent of the cr	ew (list attached in the letter) will be a	expire from June	2025 to December 2025	
All crew mentioned in the attached letter are current on type. As all our crew have done SEP Initial in an approved training facilities by CAA, we kindly request you to extend the validity of their SEP Dnits: Risk Mitigating Factors Based on training facility current availability: I. SEP instructor will conduct a theory training and take the trainees for aircraft visit; I. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). Open and close sliding window. A perform Publis Incapacitation S open and close sliding window. A perform Publis Incapacity Publis the species of the functions S. safety equipment's pre-flight check by removing the safety equipment's I. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resumption is a limited scale from June and also due to the limited number of frequencies of the flights. we are unabilited the above crew for SEP Dnills Recurrent. Associated Implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted S trained subjer and door operation consisting (ARMING, DISARMING, OPENING & CLOSING), and CLOSING, DISARMING, OPENING & CLOSING, and CLOSING, and alter the interes for aircraft visit; S trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING, CLOSING, and alter and additional attendant panel). S EP instructor will conduct a theory training and take the trainees for aircraft visit; T rainees will practice normal door operation consisting (ARMING, DISARMING, OPENING, CLOSING, and alter attendant panel). S E	of flight	s on a limited scale from .	June and also due to the limited num	ctions and the tra	ining slots availability, re as of the flights, we are	sumptio unable t
Iraining facilities by CAA, we kindly request you to extend the validity of their SEP Drills:	Propos	al				
Based on training facility current availability: 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit: 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots incapacitation 5. open and close sliding window. 6. be familier of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resumption flights on a limited scale from June and also due to the limited number of frequencies of the flights. we are unable tachedule the above crew for SEP Drills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING, CLOSIN	All crew training	mentioned in the attache facilities by CAA, we kindly	d letter are current on type. As all ou y request you to extend the validity of	r crew have don f their SEP Drills:	e SEP Initial in an appro	ved SEI
1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resumption flights on a limited scale from June and also due to the limited number of frequencies of the flights. we are unablichedule the above crew for SEP Drills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, OPENING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handset	Risk Mi	tigating Factors				
1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING). 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel) The reasons why the exemption is necessary Due to Current situation around the country situation, and travel restrictions and the training slots availability, resump of flights on a limited scale from June and also due to the limited number of frequencies of the flights. we are unablichedule the above crew for SEP Dnills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operation accessing (ARMING, DISARMING, OPENING & Crossibility of Crew getting grounded due to explain consisting (ARMING, DISARMING, OPENING & Crossibility of Crew getting and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & Crossibility of Cock) door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel).	Based	on training facility curr	ent availability:			
Due to Current situation around the country situation, and travel restrictions and the training slots availability, resump of flights on a limited scale from June and also due to the limited number of frequencies of the flights. we are unable schedule the above crew for SEP Drills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & Crossing of the flight check by removing the safety equipment's 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additionial attendant panel).	2. Trai 3. Doo 4. perfi 5. oper 6. be fi 7. safe 8. Lava 9. Airco	nees will practice normal d or emergency operation brid orm Pilots Incapacitation n and close sliding window amiliar of Cockpit door and ty equipment's pre-flight cl atory safety Check raft communication facilitie	loor operation consisting (ARMING, E ef detailing the sequence and the em r. I the functions heck by removing the safety equipme	DISARMING, OPE ergency faces. ent's		al
of flights on a limited scale from June and also due to the limited number of frequencies of the flights, we are unable schedule the above crew for SEP Drills Recurrent. Associated implication if such exemption is not granted Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & Ctooside and the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and add:Horiar attendant panel).	17-12-1	A CONTRACTOR	The reasons why the exemption	is necessary	-	170.44
Possibility of crew getting grounded due to expired SEP Drills Recurrent. Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operation accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & Ctossing and the emergency faces. 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel).	of flights	s on a limited scale from J	une and also due to the limited num	tions and the trai ber of frequencie	ning slots availability, re s of the flights, we are u	sumption unable to
Part A2 – Details of Applicant's Safety Measures Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operat in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING, CLOSING, August 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel).		As	sociated implication if such exempt	ion is not grante	d	-
Details of how the applicant proposes to ensure that an acceptable level of safety will be provided when operation accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING (CLOSING), automation of the sequence and the emergency faces. 3. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional, attendant panel).	Possibili	ty of crew getting grounde	ed due to expired SEP Drills Recurrer	nt.		
in accordance with the exemption if granted 1. SEP instructor will conduct a theory training and take the trainees for aircraft visit; 2. Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING, Aurona, S. Door emergency operation brief detailing the sequence and the emergency faces. 4. perform Pilots Incapacitation 5. open and close sliding window. 6. be familiar of Cockpit door and the functions 7. safety equipment's pre-flight check by removing the safety equipment's 8. Lavatory safety Check 9. Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional, attendant panel).		Part A	2 - Details of Applicant's	Safety Meas	ures	
 Trainees will practice normal door operation consisting (ARMING, DISARMING, OPENING & CLOSING 4. Door emergency operation brief detailing the sequence and the emergency faces. perform Pilots Incapacitation open and close sliding window. be familiar of Cockpit door and the functions safety equipment's pre-flight check by removing the safety equipment's Lavatory safety Check Aircraft communication facilities such as (handsets, area call panels, attendant indication panel and additional attendant panel). 	Details	of how the applicant pro			ill be provided when op	erating
	2. Trair 3. Door 4. perfe 5. open 6. be fa 7. safet 8. Lava 9. Aircr	nees will practice normal do remergency operation brie form Pilots Incapacitation and close sliding window. amiliar of Cockpit door and ty equipment's pre-flight ch nory safety Check aft communication facilities	oor operation consisting (ARMING, D of detailing the sequence and the eme the functions teck by removing the safety equipme	IISARMING, OPE ergency faces. nt's		al gent
evision 02 DGCAR Application for Exemption						

23 Sep 2020



	Details of h	ow ALoS will be monitored	
The extended validity will be strict	ly monitored thro	ugh AIMS.	
Review and	discuss of any kn	own safety concerns with the requirement.	State State
Nil			
List the details o	f Safety and Pub	lic Interest Factors Considered	To be completed by PACA
	Safety Fa	actors	Accepted by Regulator (Y/N)
1) for those whose SEP Drills will	expire between 1 st	June 2025 to December 2025.	Y
	Public Intere	st Factors	Accepted by Regulator (Y/N)
1) Nil			
		relevant accidents or incidents related to to or requiring exemption?	¥/N
lf	yes above provi	de details of Accident/Incident	
Indicate wh	ich other parties	may be affected by granting exemption	
Airlines		Maintenance Organizations	
Air Crew	х	Ground Staff	
Air Traffic Controllers		Training Organizations	

Air Traffic Controllers	Training Organizations	
Aerodromes	Rescue and Fire Fighting	
Security	General Public	
Other (Specify Below)		

Part A3 Application

Processing time required.

Unless the Authority agrees otherwise, an application for an exemption shall be submitted not less than thirty (30) days in advance of the proposed effective date of the exemption. Where an applicant seeks emergency processing, the application must contain supporting facts and reasons why the application was not filed in a timely manner, and the reasons it is an emergency. An application may be rejected if the Authority finds that the applicant has not justified the failure to apply in a timely manner.

Duration of Exemption				
Exemption Start Date and	l Time (in UTC)	Exemption End Date and Time (in UTC)		
01-06-2025		30-12-2025		
Revision 02 23 Sep 2020	DGCAR App	lication for Exemption		



Will the applicant seek to operate under the proposed exemption outside of Oman's Y/A airspace?

If yes indicate whether the exemption would contravene any provision of the standards and recommended practices of the International Civil Aviation Organization (ICAO)

NIL

and a set of the set o	sment, analysis or aeronautical ustify the application done	Alternative means of compliance / mitigation proposed	
Attached			
OCUMENTS ATTACHE	p		

Person Requesting Exemption (Accountable Manager / CEO / Nominated Post Holder as applicable)					
Full Name	→	Captain Tariq Al Harthy			
Email & Phone	÷	Tariq.alharthy@salamair.com			

DECLARATION BY THE APPLICANT

The applicant/holder hereby declares that the information provided in this application is correct and that no relevant information has been withheld.

Signature:

Date: 17" June 2025





Part B1 – Inspector Evaluation and recommendation of Exemption Assessment by DG CAR Focal Point

Department responsible for Evaluating Exemption	Flight Safety Department	
Inspector Responsible	Shadiya Al-Hajry	
Email of Inspector	shadiya@caa.gov.om	

	ecklist and evaluation of emption Package	Y/N	Satisfactory/ Not-satisfactory	11 11 100	ecklist and evaluation of emption Package	Y/N	Satisfactory/ Not-satisfactory
1	Has the applicant clearly specified the details of the exemption sought?	Y		7	Has the applicant submitted all relevant documents to support	Y	
2	Do the details include the reasons why the exemption is sought?	Y		8	the application?	N/A	
3	Do the details include the duration of the exemption?	Y			applicant provided the details of the certificate in force?		
4	Has the applicant clearly indicated the factors considered in making the request?	Y		9	Is the application for exemption submitted as part of an application of	N/A	
5	Do the factors include public interest and safety factors considered?	Y		10	a certificate/approval? Are there any known safety concerns that are yet to be addressed by	N	
6	Has the applicant proposed alternative means of compliance with regulatory requirements including mitigation measures to ensure safety is not compromised?	Y		11	the applicant? Has the applicant conducted and submitted a safety risk assessment for all the identified safety implications?	Ŷ	

Legal Considerations	Y/N	Specify if Yes
If granted, will this exemption infringe on any other DG-CAR regulatory requirements?	N	
If granted, will this exemption infringe on the provisions of any other laws of the State?	N	
Are there any other legal implications relative to this application?	N	

Revision 01 01 Jun 2020

DGCAR Evaluation of Exemption

.



	Hazards Associated with Granting Exemption	and the second se
Description of Hazards	Consequence	Conditions/Mitigation Measures for Exemption
Delay in conducting the SEP recurrent drills and hands-on practical training for flight and cabin crew due to training schedule limitations between June to December 2025.	Potential degradation in crew emergency preparedness and response, increased risk in emergency operations.	 Day 1: Theoretical SEP training by certified instructor, covering: Emergency procedures Safety equipment location and use Aircraft-specific exit and oxygen systems Firefighting techniques and SCP handling procedures
		Day 2: Hands-on training including:
		 Door drills using banner/video/aircraft Evacuation sequences for normal and emergency operations Practical firefighting drills for PED, seat, lavatory, and cockpit fires Life jacket, PBE, oxygen mask donning Life jacket, PBE, oxygen mask donning Familiarization with cockpit door, aircraft communication systems, lavatory checks Line checks conducted post-training

Revision 02 23 Sep 2020

DGCAR Application for Exemption

10

Civil Aviation Authority Director General of CivilAviation Regulation

Application for Exemption

=
Mitigation
Conditions/
T After C
RISK ASSESSMENT After Conditions/Mitigation In
RISK

mposed

	Probability	Severity
Post Mitigation Risk	2	
Assessment		

Terms, Conditions and Limitation.

The Public Authority for Civil Aviation will in the interests of the Aviation Safety impose or specify terms, conditions and limitation to be complied with when granting an exemption from the specified requirements: State such Terms, conditions and Limitations below:

 Exemption applies only for SEP Drills extension between June-December 2025. • Crew must complete the full mitigation program (Day 1 theoretical + Day 2 hands-on).

 The operator must maintain training records and ensure compliance with CAR OPS 1.1005 and related AMC/GM. • The Cabin Crew Training Manager shall be accountable for ensuring full implementation of mitigation measures.



 Subject to review during routine CAA safety audits and Safety Action Group (SAG) monitoring.

Subject to oversight via CAA audits and SAG reviews.

Inspector Recommendation for Granting Exemption

Based on the operator's submitted risk assessment and adequate mitigation measures, the exemption is considered acceptable with low residual risk (2E) and is therefore recommended for approval under controlled conditions.

Shadiva Al Hairi	19/06/2025g
Evaluated by:	Date:

の「「「「「「」」」」	の日本のないない	Risk Severity	ity	ACCEPTION OF	and the second se
1	A - Catastrophic	B- Hazardous	C - Major	D - Minor	E.
5 – Frequent	5A	58	SC	50	2F
4 - Occasional	4A	48	4C	40	4
3 – Remote	AE	38	30	ç	1917 action
K 2 - Improbable	2A	28	20	Contraction of the second	2
1 – Extremely Improbable	1A	18	10	9	1 7

Revision 02 23 Sep 2020

DGCAR Application for Exemption

11



Part B2 – Decision on Granting of Exemption

Department Director Re	view and Recomme	ndation for Granting Exemption
Evaluation	Y/N	Comments
Has the risk assessment been done using appropriate risk management tools?	Y	
Is the risk assessment done by the applicant adequate for all the risks identified for this exemption application?	Y	
Are the proposed alternative means of compliance, including the proposed mitigations appropriate for the management of the risks assessed?	Y	
Recommendation for Granting Exemption	Risk level after mitigation is within acceptable limits. Exemption is recommended under the stated conditions.	
Reviewed by:	Eng. Hilal Said Al Hatmi	
Date:	19/06/2025	

DIRECTOR GENERAL of CIVIL AVIATION REGUALTIONS - EXEMPTION APPROVAL/REJECTION

Exemption Granted/Denied:	Granted
Date granted: (YYYY/MM/DD)	19/06/2025
Date of Expiry (YYYY/MM/DD)	31/12/2025
Exemption to be Published by (CAN/AIC/Directive etc)	
DGCAR Name	Rawya Nasser Al-Adawi
DGCAR Signature	A Line of Constant